Bureau of Indian Standards Rajkot

Ref:- RJBO/ENF/2018-19/Press

Date- 07/06/2018

A team of 03 officers from the Bureau of Indian Standards, Rajkot Branch office conducted a search and seizure operation at M/s Shree Brahmani Engineering Company, Meghani Wadi Street, Mavdi Bypass, Rajkot- 360004.

During operation 8 Nos of LSI marked openwell submersible pumpsets were found at the firm's premises without any valid BIS Certification Marks Licence. M/s Shree Brahmani Engineering Company was found to be violating Sec 17 of the BIS Act 2016 and samples were seized as evidence for prosecution.

It is important to add here that use of ISI mark without a valid BIS Certification Marks Licence is punishable under the BIS Act 2016. Consumers are advised to remain vigilant at the time of purchase of any product and also requested to inform BIS about any possible misuse observed at the details given below.

Scientist E & Head Bureau of Indian Standards, Rajkot FP No. 364/P, Ward No.13 Kalawad Road, Rajkot- 360005 E-Mail- <u>rjbo@bis.gov.in</u>, <u>hrjbo@bis.gov.in</u>

Any information of such misuse shall be kept confidential.